

DEM USE ONLY	
	A FE
Date Received	
THE PROPERTY OF THE PROPERTY OF	

RIPDES SMALL MS4 ANNUAL REPORT GENERAL INFORMATION PAGE

RIPDES PERMIT #RIR040				management of the state of the
REPORTING PERIOD:	☑ YEAR 4 Jan 07-Dec 07		MAR	1 0 2008
PERATOR OF M84			.	
Name: CITY OF WOONS	OCKET		a and a second reserve	
Mailing Address: 169 MAI	N STREET			
City: WOONSOCKET		State: RI	Zip: 02895	Phone: (401) 767-9205
Contact Person: ALAN BR	RODD	Title: CITY E	NGINEER	
Legal status (circle one): PRI - Private PUB Other (please specify):	BPP-I	Public/Private	STA - State	FED - Federal
Name:				
Mailing Address:		State:	Zip;	Phone: ()
City:		Title:	Elb:	T Hone.
Contact Person:		Title.		
the information submitted.	with a system designed Based on my inquiry of hering the information, in eccurate, and complete	to assure that qualities the person or percently that the ire. I am aware the	ualified personnel pr ersons who manage nformation submitted at there are significa	operly gather and evaluate the system, or those person it is, to the best of my ant penalties for submitting
Print NameSL	JSAN D. MENARD			



MINIMUM CONTROL MEASURE #1: PUBLIC EDUCATION AND OUTREACH (Part IV.B.1 General Permit)

SECTION I. MEASURABLE GOALS: (For shaded areas, please provide descriptions of oppoing ac

Impl to in prog unde	(ONGOING) lementation of public education activities avolve the community in the storm water gram (indicate if activities were ertaken by permittee or other entities) (ONGOING)		FLEASE COMPLETE UNDER SECTION 18
to in progunde	ovolve the community in the storm water gram (indicate if activities were ertaken by permittee or other entities) (ONGOING)		
			PLEASE COMPLETE LINDER SECTION IL
1	BLE GOALS:	<u> </u>	
Com and	nmitment to the Storm Water Education Outreach Program through URI NEMO (OPTIONAL - DUE MARCH 2007)		
	4/24/2007 Making an Impact with LID 5/10/2007 TR-55 for Plan Reviewers	·	List name(s) of attendee(s) at each training: Alan Brodd, City Engineer.
	Atte	(OPTIONAL - DUE MARCH 2007) Attendance at the following trainings: ✓ 4/24/2007 Making an Impact with LID ☐ 5/10/2007 TR-55 for Plan Reviewers ☐ 12/12/2007 DPW Employee Training	(OPTIONAL - DUE MARCH 2007) Attendance at the following trainings:

SECTION II. **OVERALL EVALUATION:**

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:

Include information relevant to the implementation of each measurable goal, such as activities, topics addressed, audiences and pollutants targeted. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for choosing the

(Note: Identify parties responsible for achieving the measurable goals and reference any reliance on another entity for achieving measurable goals.)

The City plans to rely on the Storm Water Education and Outreach Program in cooperation with URI to meet the measurable goals in future years. The City developed a website (http://www.ci.woonsocket.ri.us/strm_wtr.htm). The website describes the general permit requirements, provides the complaint form and electronic submission of complaints, access to the SWMPP and annual reports, links to organizations with storm water quality information, a description of storm water related requirements for building permits, and recommendations for low impact development. The school department continues to incorporate environmental education into the curriculum through the pilot rain garden at Woonsocket High School, summer study courses, environmental science classes, and the clean water club. Students developed demonstration projects to showcase at the Clean Water Festival. This measure is appropriate and effective. The School Department and Engineering Department are responsible for this measure.

IV.B.1.b.2

The City plans to rely on the Storm Water Education and Outreach in cooperation with URI to meet measurable goals in future years. The City's website includes links to organizations that provide educational materials and public involvement opportunities. The City works with these groups to provide assistance with the events including student cleanups (Clean Water Festival) and the Earth Day Cleanup. The Clean Water Festival involved students from the City who participated in clean up activities and demonstrated projects that they had prepared for the festival. The City has also developed a letter and brochure to distribute to businesses which describes proper maintenance of structural BMPs. This measure has been appropriate and effective. The School Department and Engineering Department are responsible for this measure.

Additional Measurable Goals and Activities



MINIMUM CONTROL MEASURE #2: PUBLIC INVOLVEMENT/PARTICIPATION (Part IV.B.2 General Permit)

SECTION I. **MEASURABLE GOALS:** (For shaded areas, please provide descriptions of ongoing activity in SECTION II.)

Permit ID#	BMP ID	List Measurable Goal	Date(s) Completed	If goal was NOT met, briefly list reasons, current status, plans and new date for meeting the goal
IV.B.2.b.2.ii	1 and 2	Implementation of public involvement activities and description of groups engaged (ONGOING)	///////////////////////////////////////	PLEASE COMPLETE UNDER SECTIONAL
IV.B.2.b.2.iii	3	Public notice of the draft annual report and provide the opportunity for public comment (ANNUALLY)	March 8, 2008	

SECTION II. **OVERALL EVALUATION:**

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:

Include information relevant to the implementation of each measurable goal, such as types of activities and audiences/groups engaged. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for the activities chosen to

(Note: Identify parties responsible for achieving the measurable goals and reference any reliance on another entity for achieving measurable goals.)

IV.B.2.b.2.ii

The City has several groups that are active in promoting clean water including the schools and The Blackstone River Coalition. The City plans to continue the storm drain stenciling program using DPW employees on light duty on an as-available basis. This measure has been appropriate and effective. The School Department and Engineering

IV.B.2.b.2.iii

The City public noticed the annual report in the Woonsocket Call for March 13, 2008. There were no requests to review the annual report. This measure is appropriate and effective in meeting the requirement of the general permit; however, it has not promoted public involvement. The Engineering Department is responsible for this measure.

Additional Measurable Goals and Activities

PUBLIC INVOLVEMENT/PARTICIPATION cont'd

SECTION III. Public Notice Information (IV.G.2.h and IV.G.2.i) *Note: attach copy of public notice

Date of Public Notice: March 13, 2008 (estimated) How public was notified: Woonsocket Call

Was public meeting held? YES NO * If requested

Date: Where:

Summary of public comments received:

If comments that generate action are received, the annual report will be revised and resubmitted.

Planned responses or changes to the program: None



MINIMUM CONTROL MEASURE #3: ILLICIT DISCHARGE DETECTION AND ELIMINATION (Part IV.B.3 General Permit)

SECTION I. MEASURABLE GOALS: (For shaded areas, please provide descriptions of ongoing activity in SECTION II.)

Permit ID#	BMP ID	List Measurable Goal Development of an outfall map showing the location of	Date(s) Completed	Date Submitted to RIDEM	Name of document used to submit info to RIDEM and where it can be found in that document. If goal was NOT met, briefly list reasons, current status, plans and new date for meeting the goal.
IV.B.3.b.1	1	(DUE YEAR 3)	Year 3	Year 4	The outfall map was completed in Year 3, but was not submitted to DEM. The map is attached to this report.
IV.B.3.b.2	2	Tagging outfall pipes if GIS maps are not being developed (OPTIONAL ACTIVITY)			PLEASE COMPLETE UNDER SECTION N
IV.B.3.b.3		Recording of additional elements, such as location of catch basins, manholes and pipes, on an on-going basis. (ONGOING)			PLEASE COMPLETE UNDER SECTION A
IV.B.3.b.4	3	Adoption of Ordinance to prohibit and enforce illicit discharges into the MS4 (DUE YEAR 2) Signed Letter from City or Town Solicitor	Year 2	Year 2	The ordinance is attached to the Year 2 annual report.
		(DUE YEAR 2)	Year 2	Year 2	The signed letter from the Town Solicitor is attached to the Year 2 annual report.
IV.B.3.b.5.ii, iii, iv, & v	5,6,7, & 8	Implement procedures for the receipt and consideration of complaints, tracing the source of an illicit discharge, removing the source of the illicit discharge, and evaluating and assessing the program (ONGOING)			PLEASE COMPLETE NADER SECTION N
IV.B.3.b.5.vi	9	Inspection of all catch basins and manholes for illicit connections and non-storm water discharges (DUE YEAR 4)	Year 4	Year 4	A sample inspection form is attached.
IV.B.3.b.5.vii	10	Completion of two dry weather surveys, one between Jan 1 st and April 30 th and one between July 1 st and Oct 31 st . (Sanitary sewers- bacteria sampling is only required once between July 1 st and Oct 31 st) (DUE YEAR 4)	Year 4		IDDE reports have been completed and are available at the City.
IV.B.3.b.7	12	Implementation of coordinating activities with physically interconnected MS4s, including state and federal owned or operated MS4s, when illicit discharges are detected or reported (ONGOING)			PLEASE COMPLETE UNDER SECTION A
V.B.3.b.8		Implementation of referral to RIDEM of non-storm water discharges not authorized by this permit or a pre-existing permit (ONGOING)			PLEASE COMPLETE UNDER SECTION 1

		Education of public employees, businesses, and the	ILLICIT DISCHARGE DETECTION AND ELIMINATION cons
		1 90000 DUDIIL DI HAZAMS ASSOCIATOR WHE HIST	
IV.B.3.b.9	13	uischarges and improper disposal of works	X///////X//////XX//////X//////////////
		TO STORY OF THE PROPERTY OF TH	PLEASE COMPLETE UNDER SECTION 11
		Significant contributors of pollutants to the MS4.	X///////X////X///////X////////////////
B. ADDITIO	NAI ME	(ONGOING) ASURABLE GOALS:	<u> </u>
	1	TOOTABLE GOALS:	
CTION II.	OVERA	LL EVALUATION:	
ENERAL S	UMMARY	Y, STATUS, APPROPRIATENESS AND EFFECTIVENES	
		WILLIAM AND EL FECTIVENES	S OF MEASURABLE GOALS
nciude into	rmatior	n relevant to the implementation of each measura	able goal, such as activision implements
ilicit dischi	arges, p	lease explain the rationale for targeting the illicit	able goal, such as activities implemented (when reporting tracked and eliminated discharge) to comply with on-going requirements, and illicit discharge public tivities to be carried out during the next reporting and a life to the contract of the contract
	o, pica.	se mulcate rationale for the activities chosen to a	address the pollutant of concern
Note: Identi	y parties	responsible for achieving the mossyroble souls	reference any reliance on another entity for achieving measurable goals.)
/.B.3.b.1		the measurable goals and	reference any reliance on another entity for achieving measurable goals.)
/.D.3.D.1 he outfall ma	an woo de	Nichard de 2 de 1	3)
utfall investi	ation ide	prified 224 outfalls, which is 20 fears	3. Outfalls were GPS located for incorporation into the GIS database by Fuss and O'Neill. The
ppropriate a	nd effective	ve. The Engineering Department and hired consultant were	3. Outfalls were GPS located for incorporation into the GIS database by Fuss and O'Neill. The riginally identified for investigation. The outfall map is attached to this report. This measure was responsible for this measure.
		and filled consultant wen	e responsible for this measure.
/.B.3.b.2			
v.b.s.b.z lot applicable			
or applicable	••		
		•	
′.B.3.b.3			
he entire sto	m water	system has been manned on paper, and the Citylin in the	
easure has	een app	ropriate and effective in developing the City's manning. The	process of transcribing the information to electronic formats including GIS and AutoCADD. This ne Engineering Department and hired consultant are responsible for this measure.
	•	and the state of t	is Engineering Department and hired consultant are responsible for this mosques

IV.B.3.b.4

The ordinance was adopted in Year 2; a copy of the ordinance is attached to the Year 2 annual report. The ordinance is appropriate to provide a means to remove illicit discharges. Adoption of the ordinance is effective in meeting this required goal.

IV.B.3.b.5.ii, iii, iv, & v

These measurable goals were completed during the SWMPP development process prior to Year 1. Details regarding this are included in the executive summary of the SWMPP. In addition to that which is listed in the SWMPP, the Engineering Division has a 24-hr pager number for all complaints and a complaint form. Residents are informed of this purchased a camera to assist with investigation of pipeline problems in Year 2. The procedure for removal of illicit discharges involves requiring the responsible party to cease has the authority to perform repairs and charge the responsible party for the cost and fines that they may have incurred. The removal of the discharge is assessed on a case-by-exception of the procedures for tracing illicit discharges; these written procedures have not been as effective as developing procedures in the field for the specific situation.

The procedure portion of this measurable goal was completed in the SWMPP development process. Details regarding this are included in the executive summary of the SWMPP. The City inspected and cleaned approximately 60% of the City's catch basins were inspected and cleaned in Year 4. This completed the goal of cleaning all of the City's catch basins by Year 4. The Storm Water Committee, DPW, and hired consultant were responsible for procedure development and the DPW will be responsible for inspections and

IV.B.3.b.5.vii

Two dry-weather surveys were completed by Year 4. The surveys were completed by the City's consultant, Fuss and O'Neill. A report was prepared that included the results of responsible for this measure.

IV.B.3.b.7

The City has not had to coordinate with interconnected MS4s, but has coordination procedures in place. The City has working relationships with neighboring MS4s; therefore, the procedures are appropriate and expected to be effective; however, the effectiveness has yet to be determined. The Engineering Department is responsible for this measure.

IV.B.3.b.8

Procedures for referral were developed during the SWMPP prior to Year 1, with the process being put in place during Year 3. During Year 4 there were no unauthorized non-storm-water discharges that were deemed appropriate for referral to RIDEM. Since no unauthorized non-storm-water discharges have been deemed appropriate for referral to RIDEM, the appropriateness and effectiveness of this measure is yet to be determined. The Engineering Department is responsible for completion of this goal.

IV.B.3.b.9

The City provided training to municipal employees for several storm water related topics including proper BMP maintenance, BMP design, BMP selection/low impact development, flood impact minimization, and road drainage. Copies of the training that municipal employees attended were attached to the Year 3 annual report. Training has been appropriate and effective for municipal staff. The DPW is responsible for this measure.

Total Illigit Disabase Annual Control Illigit Disabase Annual	charge Inspections to Date (Part IV.G.2.m)
Total fillet Discharges Identified: None	Total Illicit Discharges Tracked: None
Total Illicit Discharges Eliminated: None	# of Complaints Received: None
# of Violations Issued: None	# of Unresolved Violations Referred to RIDEM: None
Summary of Enforcement Actions: 1 suspected illicit discharge wa	as found during IDDE inspection. The discharge was traced and found act to be

ment Actions: 1 suspected illicit discharge was found during IDDE inspection. The discharge was traced and found not to be from an illicit source.

Extent to which the MS4 system has been mapped: All of the MS4 system has been mapped on paper. The City is currently in the process of transcribing the system information

SECTION III.B Interconnections (Part IV.G.2.k and IV.G.2.l)

		C. G. C. TV. O.Z. K allu	11.0.2.1		
Interconnection:	Date Found:	Location:	Connectee:	Originating Source:	
	round.			Originating Source:	Planned and Coordinated Efforts and Activities with Connectee:
		•			



MINIMUM CONTROL MEASURE #4: CONSTRUCTION SITE STORM WATER RUNOFF CONTROL (Part IV.B.4 General Permit)

SECTION I. **MEASURABLE GOALS:** (For shaded areas, please provide descriptions of ongoing activity in SECTION II.) A. REQUIRED MEASURABLE GOALS:

Permit ID#	BMP ID	List Measurable Goal	Date(s) Completed	Date Submitted to RIDEM	Name of document used to submit info to RIDEM and where it can be found in that document. If goal was NOT met, briefly list reasons, current status, plans and new date for mosting the provided the second status.
IV.B.4.b.1	1	Adoption of Ordinance to require erosion and sediment control, control of other wastes, and sanctions to ensure compliance (DUE YEAR 2) Signed Letter from City or Town Solicitor	September 1993 and Year 2	Year 2	The ordinances are included in the Year 2 annual report as attachments.
		L (DUE YFAR 2)	Year 2	Year 2	The signed letter from the City Solicitor is included in the Year 2 annual report as an attachment.
IV.B.4.b.2		Review of 100% of plans and SWPPPs, issuance and tracking of permits for			ropore as an attachment.
IV.B.4.b.4	2 and 3	construction projects ≥ 1 acre not reviewed by other State Programs (ONGOING)			PLEASE COMPLETE UNDER SECTION II.
IV.B.4.b.6	4	Implementation of procedures to receive and consider information from the public (if relevant.) (ONGOING)			PLEASE COMPLETE UNDER SECTION II
IV.B.4.b.7	5	Inspection of 100% of all construction projects within the regulated area that discharge or have the potential to discharge to the MS4. Enforcement of erosion and sediment control measures and other measures for control of waste at construction sites. (ONGOING)			PLEASE COMPLETE UNDER SECTION I
IV.B.4.b.8	6	Implementation of procedures for referral to the State of non-compliant construction site operators			PLEASE COMPLETE UNDER SECTION 14
3. ADDITIC	NAL MEAS	(ONGOING) SURABLE GOALS:			

	CONSTRUCTION	N SITE STORM WATER RUNOFF CONTROL cont'd
·		WATER RONOFF CONTROL cont'd

SECTION II. **OVERALL EVALUATION:**

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:

Include information relevant to the implementation of each measurable goal, such as activities implemented to support the review, issuance and tracking of permits, inspections and receipt of complaints. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for the activities chosen to address the pollutant of concern.

(Note: Identify parties responsible for achieving the measurable goals and reference any reliance on another entity for achieving measurable goals.)

The City adopted a soil erosion and sediment control ordinance (using the model contained in the RI Soil Erosion and Sediment Control Handbook) on September 20, 1993 (Woonsocket Code of Ordinances Chapter 7 ½ - Erosion and Sediment Control provided in Year 1 Annual Report). The control of construction wastes is included in the illicit discharge ordinance that was adopted in Year 2. The Storm Water Committee, Building Official, and DPW - Engineering Division were responsible for this goal.

IV.B.4.b.2

IV.B.4.b.4

The City reviews all plans submitted regardless of size. Letters stating deficiencies, when present, are given to the applicant and permits are not issued until the deficiencies are corrected. 61 building permits for sites over one acre were issued in Year 4. The City's review process has been appropriate and effective. The Engineering Department is responsible for reviews and issuing permits. The City tracks reviews and permits using Microsoft Outlook. A summarized list of reviews is attached.

IV.B.4.b.6

The procedures for this measure were established during SWMPP development prior to Year 1. Public comments are received by the City Engineer, or another appropriate department at the City. None of the comments have been referred to DEM thus far. This measure has been appropriate and effective in addressing public concerns about soil erosion and sedimentation control involving new development. The Town Engineer and Building Department are responsible for this measure.

IV.B.4.b.7

The City inspects all sites during several stages of construction. The City is in the process of updating the inspection tracking mechanism. Enforcement of the Soil Erosion and Sediment Control Ordinance is through the Building Inspection Office, but all construction sites are inspected by both the Building Inspection Office and the Engineering Division. The Building Inspection and Engineering Division personnel are all aware of the City's SESC ordinance and cooperate to see that it is enforced. The number of inspections at an individual site varies depending on the magnitude of the job site. The Engineering Division inspected approximately 1,005 sites (including small items such as sidewalk blockages) in Year 4, with each site being inspected at least once. Currently, DPW-Engineering staff is on site whenever any work is being done pertaining to the storm water utilities and/or in-ground storm water structures (e.g., catch basins, Vortechs units). Any erosion issues are addressed immediately through informal notification. Formal enforcement actions are taken if necessary. There were no formal enforcement measures taken in Year 4. The Storm Water Committee, Engineering Division, and Building

CONSTRUCTION SITE STORM WATER RUNOFF CONTROL cont'd

IV.B.4.b.8

The procedures for this measure were established during SWMPP development prior to Year 1. Any site problems found by Engineering Division staff are directed to the City Engineer and/or the Construction Manager for enforcement. The Engineering Division can close down and retract issued permits for any construction site found to be non-Division is responsible for this goal.

Additional Measurable Goals and Activities

SECTION III. A Plan and SWPPP Reviews during Year 4 (2007)

of Construction Reviews completed: 61 over one acre, 1,005 total

Summary of Reviews and Findings: Comments were made by the City Engineer and addressed by the site designer. All of the sites that submitted plans in Year 4 were permitted and have begun work.

SECTION III.B Erosion and Sediment Control Inspections during Year 4 (2007) (Part IV.G.2.n)

" .com	ections during Year 4 (2007) (Part IV.G.2.n)
# of Site Inspections: 61+	# of Complaints Received: None
# of Violations Issued: None	# of Unresolved Violations Referred to RIDEM: None
Summary of Enforcement Actions: No formal enforcement	actions were necessary during Year 4.



MINIMUM CONTROL MEASURE #5: POST CONSTRUCTION STORM WATER MANAGEMENT IN NEW DEVELOPMENT AND REDEVELOPMENT (Part IV.B.5 General Permit)

SECTION I. MEASURABLE GOALS: (For shaded areas, please provide descriptions of ongoing activity in SECTION II.)

Permit ID#	BMP ID	List Measurable Goal	Date(s) Completed	Date Submitted to RIDEM	Name of document used to submit info to RIDEM and where is can be found in that document. If goal was NOT met, briefly list reasons, current status, plans and new date for meeting the
IV.B.5.b.4	3	Review of 100% of plans for development projects one or more acres not reviewed by other State Programs (ONGOING)			and new date for meeting the goal.
IV.B.5.b.5	4	Coordination with existing State programs requiring post-construction storm water management (ONGOING)			PLEASE COMPLETE UNDER SECTION 11
IV.B.5.b.6	5	Implementation of referral to the State of new discharges of storm water associated with industrial activity (ONGOING)			PLEASE COMPLETE UNDER SECTION II
IV.B.5.b.9	6	Adoption of Ordinance to address post-construction runoff from new development and redevelopment (DUE YEAR 2) Signed Letter from City or Town Solicitor	Year 2	Year 2	The ordinance is included in the Year 2 annual report as an attachment.
IV.B.5.b.10	7	(DUE YEAR 2) Post-construction inspections of BMPs and inspect 100% of all development ≥ 1 acre within the regulated area that discharges to the MS4 (ONGOING)	Year 2	Year 2	The signed letter from the City Solicitor is included in the Year 2 annual report as an attachment.
V.B.5.b.11		Implementation of how long-term O&M of selected BMPs for new and re-development will be identified, tracked and enforced (ONGOING)			PLEASE COMPLETE UNDER SECTION 1
V.B.5.b.12	8	Identification of existing structural BMPs (ONGOING)			55 E 165 E 1644
3. ADDITION	AL MEASU	JRABLE GOALS:			######################################

POST CONSTRUCTION STORM WATER MANAGEMENT IN NEW DEVELOPMENT AND REDEVELOPMENT cont'd

SECTION II. **OVERALL EVALUATION:**

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:

Include information relevant to the implementation of each measurable goal, such as activities implemented to support the review, issuance and tracking of permits, inspections and receipt of complaints, etc. Please indicate if any projects have incorporated the use of Low Impact Development techniques. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for the

IV.B.5.b.4

Currently, the Engineering Division has developed a system to perform thorough site plan reviews on all projects containing structural storm-water BMPs. All site plans that include storm water provisions are reviewed by the Engineering Division. Each project's plan(s) and status are recorded in Microsoft Outlook for quick reference by any City official. Reviews have been appropriate and effective. The DPW Engineering Division and Building Department are responsible for reviews.

IV.B.5.b.5

The City requires that applicants receive state approvals before applications will be accepted and approved. Notwithstanding, the City does not plan to relying on state approvals and will continue to review plans for storm water management. It is appropriate to determine how plan review will account for state program review. Reviewing plans and referring applicants to the state when required has been effective. The Engineering Division and the Building Official are responsible for referring applicants for state reviews when

IV.B.5.b.6

The procedures for this measure were established during SWMPP development prior to Year 1. The Town Engineer requires new applicants to obtain state permits prior to approving new industrial discharges. Details regarding this are included in the executive summary of the SWMPP. It is appropriate and effective to refer new industrial discharges to the state. No new industrial discharges were reported in Year 4, so the effectiveness is yet to be determined. The Storm Water Committee, DPW, and City Council are

IV.B.5.b.9

An ordinance was adopted Year 2 (Post Construction – Storm Water Control Ordinance), which is attached to the Year 2 annual report. The Engineering Division requires and reviews a maintenance plan for all storm water structures as part of the plan review process. It is appropriate to adopt a regulatory mechanism for post-construction runoff. The mechanism is effective in requiring applicants to address runoff. The Storm Water Committee and City Council are responsible for this goal.

IV.B.5.b.10

The City maintains a list of structural BMPs that are in place throughout the City. Owners of properties with detention ponds are provided with letter and an informational brochure when deficiencies are noticed. The City currently is responsible for eight detention ponds that they inspect and maintain periodically. The City has established a system for taking complaints and addresses issues with property owners as needed. It is appropriate to inspect BMPs once constructed. The Building Department and DPW-Engineering Division are responsible for implementing the inspection procedures and including in the City's regulations and/or requirements.

IV.B.5.b.11

Procedures for implementation of long-term O&M for selected BMPs were established during SWMPP development prior to Year 1. O&M procedure regulations are included in the City Ordinance for post construction storm water management. The City Ordinance requires that BMPs be deeded to the corresponding homeowners association with language stipulating that they properly operate and maintain the BMP. Identifying, tracking, and enforcing long-term O&M procedures for selected BMPs are appropriate and effective measures. The City Council was responsible for adopting this regulation, with the DPW responsible for enforcement.

IV.B.5.b.12

The existing BMPs have been identified, and new BMPs are added as the City issues occupancy certificates. This measure has been appropriate and effective. The Building

POST CONSTRUCTION STORM WATER MANAGEMENT IN NEW DEVELOPMENT AND REDEVELOPMENT cont'd

Additional Measurable Goals and Activities

SECTION III.A. Plan and SWPPP Reviews during Year 4 (2007)

of Post-Construction Reviews completed: 2

Summary of Reviews and Finding: Sites were reviewed and approved for proper installation of BMPs.

SECTION III.B. Post Construction Inspections during Year 4 (2007): Proper Installation of Structural BMPs (Part IV.G.2.o)

# of Site Inspections: 2	ear 4 (2007): Proper Installation of Structural BMPs (Part IV.G.2.o)
	# of Complaints Received: None
# of Violations Issued: None	# of Unresolved Violations Referred to RIDEM: None
Summary of Enforcement Actions: Sites were in compliance there	efore no enforcement actions were taken.

SECTION III.C. Post Construction Inspections during Year 4 (2007): Proper Operation and Maintenance of Structural BMPs (Part IV.G.2.p)

	# of Site Inspections: 16	# of Compleints B
		# of Complaints Received: None
	# 0f Violations Issued: None	
	Summary of Enforcement Actions: No enforcement actions were ta	# of Unresolved Violations Referred to RIDEM: None
	The onlocement actions were ta	iken.
1		



MINIMUM CONTROL MEASURE #6: POLLUTION PREVENTION AND GOOD HOUSEKEEPING IN MUNICIPAL OPERATIONS (Part IV.B.6 General Permit)

SECTION I. **MEASURABLE GOALS:** (For shaded areas, please provide descriptions of ongoing activity in SECTION II.)

Permit ID#	BMP ID	List Measurable Goal	Date(s) Completed	If goal was NOT met, briefly list reasons, current status, plans
IV.B.6.b.1.i	1	Identification, location and description of all municipally owned structural BMPs (ONGOING)		and new date for meeting the goal
IV.B.6.b.1.ii	2	Inspection and cleaning BMPs (ONGOING)		PLEASE COMPLETE LINDER SECTION IL
IV.B.6.b.1.iii	3	Annual catch basin inspection and cleaning program (ANNUALLY)	Year 4	
IV.B.6.b.1.iv	4	Minimize erosion of road side shoulders and ditches by requiring stabilization of those areas (ONGOING)		PLEASE COMPLETE LINDER SECTION N
IV.B.6.b.1.v	5	Identify and report annually the known discharges causing scouring at outfall pipes or outfalls with excessive sedimentation and a description of all corrective actions (ONGOING / ANNUALLY)		PLEASE COMPLETE UNDER SECTION IL
V.B.6.b.1.vi	6	Annual road sweeping of all streets and roads within the regulated area annually (ANNUALLY)	Year 1 Year 2 Year 3	
V.B.6.b.1.vii	7	Maintenance activities, schedules and long-term inspection for controls to reduce floatables (ONGOING)	Year 4	PLEASE COMPLETE UNDER SECTION IL
V.B.6.b.1.viii	8	Proper disposal of removed waste from the MS4 (ONGOING)		PLEASE COMPLETE UNDER SECTION A
V.B.6.b.4	10	Municipally owned non-Industrial facilities must develop and implement BMPs for O&M and Good Housekeeping, as well as corrective actions designed to eliminate and/or minimize the discharge of pollutants to waters of the State (DUE YEAR 4)	Year 4	

POST CONSTRUCTION STORM WATER MANAGEMENT IN NEW DEVELOPMENT AND REDEVELOPMENT.

IV.B.6.b.5		Reporting and tracking of inspections, comprehensive site evaluations, corrective actions implemented and scheduled improvements to minimize the discharge of pollutants at industrial facilities owned and operated by the municipality	PLEASE COMPLETE UNDER SECTION 14.
IV.B.6.b.6	13	(ONGOING) Implementation of employee training programs that will be used to prevent and reduce storm water pollution	DI FASS PONSTALLER
IV.B.6.b.7	11	(ONGOING) Implementation of procedures for assessing potential water quality impacts to existing and new flow management projects (ONGOING)	PLEASE COMPLETE LINDER SECTION 11
B. ADDITION	IAL MEA	SURABLE GOALS:	

SECTION II. OVERALL EVALUATION:

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:

Include information relevant to the implementation of each measurable goal, such as activities and practices used to address on-going requirements. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for the activities chosen to address the pollutant of concern.

(Note: Identify parties responsible for achieving the measurable goals and reference any reliance on another entity for achieving measurable goals.)

IV.B.6.b.1.i

The DPW has identified structural BMPs and adds new BMPs when the City takes ownership. This measure is appropriate and effective. The Storm Water Committee and DPW are responsible for the completion and implementation of this goal.

IV.B.6.b.1.ii

The City inspects and maintains its BMPs on an as needed basis. Inspection and maintenance of the City's BMPs is appropriate and effective. The Engineering Division is

IV.B.6.b.1.iii

The City has developed an annual catch basin cleaning program, a summary of which was attached to the Year 3 annual report. The program consists of cleaning the catch basins using a grid system to track the catch basins that have been cleaned. Certain portions of the City, specifically the low lying areas of the developed portions of the City are cleaned more regularly. In Year 4, the City cleaned approximately 60% of their catch basins. A list of catch basins that were found to be deficient during inspections is attached. The Storm Water Committee and DPW were responsible for the completion of this goal.

POST CONSTRUCTION STORM WATER MANAGEMENT IN NEW DEVELOPMENT AND REDEVELOPMENT cont'd

IV.B.6.b.1.iv

This measurable goal was completed in the SWMPP development process. Details regarding this are included in the executive summary of the SWMPP. In the City, most of the roadways are curbed and have sidewalks. Any roadway with a shoulder or ditch in need of repair is immediately addressed. It is usually a property owner or municipal employee that notifies the DPW of a problem and the Highway Division addresses it. Inspections during road work by municipal employees are an appropriate way of observing any erosion of road side shoulders and ditches. Erosive conditions that are found are treated with rip-rap or vegetative stabilization. Erosive conditions are currently corrected when discovered, which is effective in preventing further erosion. The Storm Water Committee and DPW are responsible for the completion of this goal. Fewer than 10 roadside

IV.B.6.b.1.v

The City implemented a regular outfall inspection program after the outfalls were mapped in Year 3. The mapping includes an initial inspection of the outfalls to create a priority list for future years. The Storm Water Committee and DPW are responsible for the completion of this goal.

IV.B.6.b.1.vi

The City committed to the measurable goal of sweeping all municipal streets in the submitted SWMPP. The town owns three street sweeper trucks, and presently, all City streets are cleaned at least once a year based on the grid system. In Year 4, the City swept the all of their streets at least once. The DPW is responsible for the completion of this goal.

IV.B.6.b.1.vii

The City currently requires that all new and redevelopment projects include installation of catch basin hoods. The City evaluates the need for retrofits as funds become available and targets priority areas. Catch basin inlet grates are cleaned when catch basins are inspected or when municipal employees report a need for cleaning. The annual catch basin cleaning program includes removal of floatables. The need for additional cleaning will be documented on inspection forms. Floatables are also collected by Woonsocket's Routine Litter Patrol setup by the Highway Department during daily litter pickup activities. Trash cans are provided at frequented pedestrian areas including Main Street and the RIPTA bus stops. These trash cans are empted daily Monday through Friday. Catch basin grates are inspected for debris after heavy wind and/or rain by Highway personnel. A tracking system is being developed for cleaning and repairs. The DPW is responsible for the completion of this goal. IV.B.6.b.1.viii

This measurable goal was completed in the SWMPP development process. Details regarding this are included in the executive summary of the SWMPP. The City met with the Solid Waste Recycling Advisory Committee that was developed in Year 2. The City hired a consultant to increase city-wide recycling. The DPW and hired consultant are responsible for the completion of this goal. The DPW and Fire Department are responsible for continued recordkeeping.

IV.B.6.b.4

An O&M and good housekeeping program was developed during the SWMPP development process. Details regarding this are included in Section 9.0 of the SWMPP. The City assessed the non-industrial facilities with the potential to introduce pollutants to their storm water discharges during the SWMPP development process. Many possible BMPs were identified. These BMPs will be implemented throughout the term of this permit as funds and/or labor become available. This assessment during the SWMPP process has given the City a good starting point for the implementation of the O&M and pollution prevention program at non-industrial facilities under the City's control. The Storm Water Committee, DPW, and hired consultant were responsible for the completion of this goal, and the DPW is responsible for the implementation of the BMPs as funds become

IV.B.6.b.5

The general permit requires that municipally owned facilities with storm water discharges associated with industrial activity, implement a site specific storm water pollution prevention plan (SWPPP). There is one municipally owned industrial facilities with a site specific SWPPP in Woonsocket, which is the Highway Garage. Regular inspections of this facility are performed by members of the Highway Department. This is an appropriate and effective measure for ensuring that municipally owned industrial facilities are not polluting the City's storm water system. The DPW is responsible for this measurable goal.

IN/DOLO		POST CONSTRUCTION STORM W	ATER MANAGEMENT IN NEW DEVELO	DEMENT AND DEDENIE
offers free training application, which IV.B.6.b.7 Currently, flow man management proje municipal projects.	to DPW employees on whas been effective. The magement is addressed ects during the planning and the Storm Water Com	Education and Outreach program for training are included in Section 9.0 of the SWMPP anics that includes storm water awareness. Various issues. It is appropriate to train munt storm Water Committee and DPW are responded to the step plan review process as part of and design stages of municipal projects. It is mittee and DPW are responsible for the committee and DPW	needs in future years. The current program value and the Response to Comments. The City is Additionally, the City is a member of the Rhodicipal employees. Training that is being provide consible for this goal.	vas evaluated as part of the SWMPP is teaming with Fuss & O'Neill, Inc. to provide e Island Public Works Association, which ed is chosen because it is appropriate for the
Additional Measura	able Goals and Activities			
SECTION III.A St	ructural BMPs (Part	IV.B.6.b.1.i)		
BMP ID:	Location:	Name of BMP Owner/Operator:	Description	on of BMP:
See list attached				
SECTION III.B Di	scharges Causing S	couring or Excessive Sedimentation	(Part IV.B.6.b.1.v)	
Outfall ID:	Location:	Description of Problem:	Description of Remediation Taken, include dates:	Receiving Water Body Name/Description:
	·			
SECTION III.C No ac	ote any planned mun ctivities to promote i	nicipal construction projects/opportunn nitration and recharge (Part IV.G.2.j)	nities to incorporate water quality BMP	s, low impact development, or
	<u> </u>		on that has been collected and analyze	d. This includes any type of data
None tracked, infra	structure improvements	are made as funds become available.		



TOTAL MAXIMUM DAILY LOAD (TMDL) or other Water Quality Determination REQUIREMENTS

SECTION I. If you have been notified that discharges from your MS4 require non-structural or structural storm water controls based on an approved TMDL or other water quality determination, please provide an assessment of the progress towards meeting the requirements for the control of storm water identified in the approved TMDL (Part IV.G.2.d). Please indicate rationale for the activities chosen to address the pollutant of concern.

The City does not have approved TMDLs storm water.

 CITY OF WOONSOCKET

DEPARTMENT OF PUBLIC WORKS

ENGINEERING DIVISION

DATE OF INSPECTION

LOCATION	DESCRIPTON	OWNER	MAP	LOT
PARK EAST DR / CVS DRIVE		CITY OF WOONSOCKET	F7	56-15
WALMART		WALMART STORES 702 SOUTHWEST 8TH STREET BENTONVILLE AR 72716	В7	52-6
LOWES		114 DIAMOND HILL RD II LLC 1 PROVIDENCE WASHINGTON PLACE 9TH FLOOR PROVIDENCE RI 02903	В7	52-20
BROOKHEAVEN POND		DONNA JEAN 1305 BROOKHAVEN LANE WOONSOCKET RI 02895	C8	58-31
BROOKHEAVEN POND		DONNA JEAN 1305 BROOKHAVEN LANE WOONSOCKET RI 02895	C8	58-31
TARA LANE/ LEDGEWOOD DR.		CITY OF WOONSOCKET	C7	58-37
EAST WOONSOCKET		CITY OF WOONSOCKET	В7	57-88
HOLLY SPRINGS		WILFRED DESROSIERS 306 HOLLY LANE WOONSOCKET RI 02895	D7	55-203
OREGON AVE		CITY OF WOONSOCKET	D7	59-2
DIAMONDHILL RD		CITY OF WOONSOCKET	B7	53-5
ROBINSON STREET POTHIER SCHOOL		CITY OF WOONSOCKET	C5	36-136
PARK DRIVE & HARTFORD AVE		OAKLAND GROVE ASSOCATES 560 CUMBERLAND HILL RD WOONSOCKET RI 02895	E6	41-29
1026 PARK EAST DRIVE		UNICOM INCORPORATED 1026 PARK EAST DRIVE WOONSOCKET, RI 02895 (401) 765-3000	D7	59-13
300 PARK EAST DRIVE		TECHNIC, INC 300 PARK EAST DRIVE WOONSOCKET, RI 02895	E6	50-51
500 PARK EAST DRIVE		RI INDUSTRIAL FACILITIES CORP 500 PARK EAST DRIVE WOONSOCKET, RI	E7	50-211
1 CVS DRIVE		CVS 1 CVS DRIVE WOONSOCKET, RI	F7	51-2
811 PARK EAST DRIVE		RETAIL GRAPHICS 811 PARK EAST DRIVE WOONSOCKET, RI 02895	E7	56-6

Appendix E: Maintenance Inspection Checklist Infiltration Basins and Trenches

Project/Location: CIS PAVE	
	•
"As Built" Plans Available? VES Date/Time: 2/13/67	
Days Since Previous Rainfall and Rainfall Amount:	
Inspector: LARRY ENCIGITY	

Maintenance Item	Satisfactory	Unsatisfactory	Comments
1. Debris Cleanout			
Basin bottom or trench surface clear of debris		NEEDS Som	E GEANING
Inlet/Inflow pipes clear of debris	OK		
Overflow spillway clear of debris	OK		
Outlet clear of debris	al		
2. Sediment Traps or Forebays NA			
Sedimentation noted			
Greater than 50% of storage volume remaining			
3. Vegetation (Basins)			
Mowing performed as necessary		NEED 3 SOM	E CHERNING
No evidence of erosion	CX	. ,	
. Dewatering			
Basin/Trench dewaters between storms	OK		
 Drawdown time does not exceed 36 to 48 hours 	Och		
. Sediment Accumulation			
Approximate depth of accumulated sediment			
Inlets			
Good condition	OV		
No evidence of erosion	OU		
Outlet/Overflow Spillway ///			
Good condition, no need for repair			
No evidence of erosion			
Aggregate Repairs (Trench)			
Surface of aggregate clean	OV.		
Top layer of stone does not need replacement			
Trench does not need rehabilitation			
Structural Repairs			
Embankment in good repair	ou		
Site slopes are stable			
No evidence of erosion			

Rhode Island Stormwater Manual Ap.

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Comments
10. Fences/Access Repairs		<u> </u>	
Fences in good condition	01/2		
No damage which would allow undesired entry			
Access point in good condition		W	
Locks and gate function property			
o Be Completed By (Date):			
•			

Source: Adapted from Watershed Management Institute, Inc. 1997. Operation, Maintenance, and Management of Stormwater Management Systems. In cooperation with U.S. Environmental Protection Agency, Office of Water. Washington, D.C.

9. Structural Repairs

Trench does not need rehabilitation

Embankment in good repair Site slopes are stable No evidence of erosion

Appendix E: Maintenance Inspection Checklist Infiltration Basins and Trenches

Project/Location: 1026 PARKEAST DRIVE

"As Built" Plans Available? VES				
Date/Time: 2/13/07				
/ /				
Days Since Previous Rainfall and Rainfall Amount:	*	· · · · · · · · · · · · · · · · · · ·		
Inspector: LARRY ENRIGHT				
/ /				
Maintenance Item	Satisfactory	Unsatisfactory	Comments	33
1. Debris Cleanout	The Contract of the	42 m/2 18 m/3 (19 m/2	The control of the co	<u> </u>
Basin bottom or trench surface clear of debris	7	mile Con	14/20080	
Inlet/Inflow pipes clear of debris		Rivered 7	20100	
Overflow spillway clear of debris		Dave !	-DALC	
Outlet clear of debris		BOUSET	70000	
2. Sediment Traps or Forebays		SKUCH	11988	
Sedimentation noted		Same_		_
Greater than 50% of storage volume remaining		SUME		_
3. Vegetation (Basins)				
Mowing performed as necessary		NO		\dashv
No evidence of erosion	DK	0000		
4. Dewatering	1 000			_
Basin/Trench dewaters between storms	English A	T DAK &	F INSP,	
Drawdown time does not exceed 36 to 48 hours	120117	1 ////	THOY,	-
5. Sediment Accumulation				
Approximate depth of accumulated sediment				
6. Inlete				
Good condition	7	TREE (lowing AT	بر مرسول
No evidence of erosion	1	1122	10 W 110 W 119	also Elec
7. Outlet/Overflow Spillway	<u></u>	~L	and the state of t	
Good condition, no need for repair				-
No evidence of erosion			Antonios, es plante a constructiva de la construcción de la construcci	-
8. Aggregate Repairs (Trench)			remains and the second	
Surface of aggregate clean	OU			-
Top layer of stone does not need replacement				1

Rhode Island Stormwater Manual

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Comments
10. Fences/Access Repairs 10 FEDCH	<u> </u>		
Fences in good condition			
No damage which would allow undesired entry		, , , , , , , , , , , , , , , , , , ,	***************************************
Access point in good condition			***************************************
Locks and gate function property		· · · · · · · · · · · · · · · · · · ·	
To Be Completed By (Date):			

Source: Adapted from Watershed Management Institute, Inc. 1997. Operation, Maintenance, and Management of Stormwater Management Systems. In cooperation with U.S. Environmental Protection Agency, Office of Water. Washington, D.C.

Appendix E: Maintenance Inspection Checklist Infiltration Basins and Trenches

Project/Location: 30 PARK FAST DR.
"As Built" Plans Available?
Date/Time: 2/13/07 344 PM
Days Since Previous Rainfall and Rainfall Amount:
Inspector: ARRY ENRIGHT

Maintenance Item	Satisfactory	Unsatisfactory	Comments
1. Debris Cleanout		<u>Linear de la companya de la company</u>	4.00
Basin bottom or trench surface clear of debris		No	VERY LITTLE CIEN
Inlet/Inflow pipes clear of debris	DK		News
Overflow spillway clear of debris	OK		
Outlet clear of debris	OK		
. Sediment Traps or Forebays		**************************************	J
Sedimentation noted	04		
Greater than 50% of storage volume remaining	01/	THE BERTHAL AND REAL PROPERTY AND REAL PROPERTY OF THE PROPERT	
. Vegetation (Basins)			
Mowing performed as necessary	DK		
No evidence of erosion	OK	***************************************	
Dewatering		·····	
Basin/Trench dewaters between storms	OK		
Drawdown time does not exceed 36 to 48 hours	DIK		**************************************
Sediment Accumulation	L	·······	
Approximate depth of accumulated sediment	OK		
Inlets	······································	······································	· · · · · · · · · · · · · · · · · · ·
Good condition	OK	<u> </u>	
No evidence of crosion	OK		**************************************
Outlet/Overflow Spillway			***************************************
Good condition, no need for repair	01.		**************************************
No evidence of erosion	DK		***********
Aggregate Repairs (Trench)			
Surface of aggregate clean	OK	· 1	***************************************
Top layer of stone does not need replacement	OK		
Trench does not need rehabilitation	DK		· · · · · · · · · · · · · · · · · · ·
Structural Repairs			
Embankment in good repair	OK		
Site slopes are stable	ok	~~~	
No evidence of erosion	OK		

Rhode Island Stormwater Manual

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Comments
10. Fences/Access Repairs		<u></u>	
Fences in good condition	NA FENC	1/2	
No damage which would allow undesired entry			
Access point in good condition			
Locks and gate function property			
To Be Completed By (Date):			

Source: Adapted from Watershed Management Institute, Inc. 1997. Operation, Maintenance, and Management of Stormwater Management Systems. In cooperation with U.S. Environmental Protection Agency, Office of Water. Washington, D.C.

No evidence of erosion

Appendix E: Maintenance Inspection Checklist Infiltration Basins and Trenches

Project/Location: 500 /ARK EAS	IT IR			
"As Built" Plans Available? WS				
. Date/Time: 2/13/07				
. Date/Time: 0/10/0				
Days Since Previous Rainfall and Rainfall Amounts				
Inspector: LARRY ENGIGHT	/			
hispector.				
Maintenance Item	Satisfactory	Unsatisfactory	Comments	
1. Debris Cleanout			1 Staye in part of properties in the	
Basin bottom or trench surface clear of debris		Some DE	ELS STUMPS	70
Inlet/Inflow pipes clear of debris	OU	Some pa	MO J SIOMY S	QQW
Overflow spillway clear of debris	OX			
Outlet clear of debris	0//			
2. Sediment Traps or Forebays	1 0/	I		
Sedimentation noted .	NINE			
Greater than 50% of storage volume remaining				
3. Vegetation (Basins)				
Mowing performed as necessary		NEEDS So	ME CLESAVIN	
No evidence of erosion	125	present co	ME CESANIN	6
. Dewatering		<u></u>		
Basin/Trench dewaters between storms	N/			
Drawdown time does not exceed 36 to 48 hours	160			-
Sediment Accumulation V/A			***************************************	
Approximate depth of accumulated sediment				
Inlets	——————————————————————————————————————		**************************************	
Good condition	OK			
No evidence of erosion	OX		***************************************	-
Outlet/Overflow Spillway			***************************************	
Good condition, no need for repair	T			-
No evidence of erosion		************************		-
Aggregate Repairs (Trench)				
Surface of aggregate clean	ck			_
Top layer of stone does not need replacement				
Trench does not need rehabilitation	1		·	-
Structural Repairs	 		Many Carlot	
Embankment in good repair	OK			-
Site slopes are stable	 			

Rhode Island Stormwater Manual

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Comments
10. Fences/Access Repairs NO FENCE		<u> </u>	1
Fences in good condition			
No damage which would allow undesized entry			
Access point in good condition			
Locks and gate function property		**************************************	
Го Ве Completed By (Date);			:

Source: Adapted from Watershed Management Institute, Inc. 1997. Operation, Maintenance, and Management of Stormwater Management Systems. In cooperation with U.S. Environmental Protection Agency, Office of Water. Washington, D.C.

Appendix E: Maintenance Inspection Checklist Infiltration Basins and Trenches

Project/Location: 811 /ARK EAST DR.	
"As Built" Plans Available? VES	
"As Built" Plans Available? 15S Date/Time: 2/13/07	**************************************
Days Since Previous Rainfall and Rainfall Amount:	
Inspector: LARRY ENRIGHT	

Maintenance Item	Satisfactory	Uneatisfactory	Comments
1. Debris Cleanout	<u> </u>	E	
Basin bottom or trench surface clear of debris		STUMPS/SOME	DERRIS
Inlet/Inflow pipes clear of debris	VES	7	
Overflow spillway clear of debris	an		
Outlet clear of debris	OK	•	
2. Sediment Traps or Forebays	***************************************		
Sedimentation noted	OK		
Greater than 50% of storage volume remaining	OV		و من من من من من د در د
3. Vegetation (Basins)	· · · · · · · · · · · · · · · · · · ·		**************************************
Mowing performed as necessary	122	**	
No evidence of erosion	84	***************************************	**
. Dewatering			
Basin/Trench dewaters between storms	OK.		
Drawdown time does not exceed 36 to 48 hours	OK		######################################
. Sediment Accumulation	······································		
Approximate depth of accumulated sediment	DK		minerani likk ekinde ekin ekin ekin menerakanan menandarikan hikur pili 14.5 dan eki
Inlets		······································	
Good condition	OK		**************************************
No evidence of erosion	01/		
Outlet/Overflow Spillway		**************************************	
Good condition, no need for repair			***************************************
No evidence of erosion			**************************************
Aggregate Repairs (Trench)	· · · · · · · · · · · · · · · · · · ·		
Surface of aggregate clean	06		
Top layer of stone does not need replacement	OK		
Trench does not need rehabilitation	OK		
Structural Repairs			
Embankment in good repair	04		
Site slopes are stable	OV		والمتعادلة والمتواجعة والمتعادلة والمتعادلة والمتعادلة والمتعادلة والمتعادلة والمتعادلة والمتعادلة والمتعادلة
No evidence of erosion	OV		414-914-914-914-914-914-914-914-914-914-

Rhode Island Stormwater Manual

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Commente
10. Fences/Access Repairs NO FENCE		<u> </u>	And the second s
Fences in good condition			
No damage which would allow undesired entry			
Access point in good condition			
Locks and gate function property	***************************************		
To Be Completed By (Date):			

Source: Adapted from Watershed Management Institute, Inc. 1997. Operation, Maintenance, and Management of Stormwater Management Systems. In cooperation with U.S. Environmental Protection Agency, Office of Water. Washington, D.C.

Appendix E: Maintenance Inspection Checklist Infiltration Basins and Trenches BROOK HEAUEN "As Built" Plans Available? Date/Time: Days Since Previous Rainfall and Rainfall Amount: Maintenance Item Satisfactory Unsatisfactory Comments 1. Debris Cleanout Basin bottom or trench surface clear of debris Inlet/Inflow pipes clear of debris Overflow spillway clear of debris • Outlet clear of debris 2. Sediment Traps or Forebays Sedimentation noted Greater than 50% of storage volume remaining 3. Vegetation (Basins) Mowing performed as necessary No evidence of erosion 4. Dewatering Basin/Trench dewaters between storms Drawdown time does not exceed 36 to 48 hours 5. Sediment Accumulation Approximate depth of accumulated sediment 6. Inlete NEEDS CLEMINS Good condition No evidence of erosion 7. Outlet/Overflow Spillway Good condition, no need for repair DK No evidence of erosion 8. Aggregate Repairs (Trench) Surface of aggregate clean Top layer of stone does not need replacement Trench does not need rehabilitation 9. Structural Repairs LARGE TREAS ALL AROUND Embankment in good repair Site slopes are stable

No evidence of erosion

Rhode Island Stormwater Manual

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Commente
10. Fences/Access Repairs No Fine	·····		
Fences in good condition		1	<u> </u>
No damage which would allow undesired entry			
Access point in good condition			
Locks and gate function property Actions to Be Taken:			
To Be Completed By (Date):			

Source: Adapted from Watershed Management Institute, Inc. 1997. Operation, Maintenance, and Management of Stormwater Management Systems. In cooperation with U.S. Environmental Protection Agency, Office of Water. Washington, D.C.

Appendix E: Maintenance Inspection Checklist Stormwater Ponds and Wetlands	6
Project/Location: DIAMOND Hus RD (DARLING)	(POND)
"As Built" Plans Available? , NO	
Date/Time: 2/13/67	
Days Since Previous Rainfall and Rainfall Amount:	
Inspector: LARRY ENRIGHT	

Maintenance Item	Satisfactory	Unsatisfactory	Comments
Embankment and Emergency Spillway			
Vegetation and ground cover adequate		BUGR CA	POWN
Embankment erosion		WES	
Animal burrows		VES	
Unauthorized planting		LIES	***************************************
 Cracking, bulging, or sliding of embankment/dam N/A 		y	
a. Upstream face			4.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1
b. Downstream face			**************************************
c. At or beyond toe			····
d. Emergency spillway			
• Pond, toe & chimney drains clear and functioning N/A			
• Seeps/leaks on downstream face N/A			
Slope protection or riprap failure			
Vertical/horizontal alignment of top of dam "As-Built" 1	A		
Emergency spillway clear of obstructions and debris			
Other (specify)			
Riser and Principal Spillway		··············	
Low flow orifice obstructed		VES	**************************************
Low flow trash rack obstructed with debris		VES	المستعدد المستعدد المستعدد والمستعدد والمستعد والمستعدد والمستعد والمستعدد و
Weir trash rack obstructed with debris		WES	
Excessive sediment accumulation insider ciser		WES	and the state of t
Concrete/masonry condition riser and barrels			errore announced as a polythy demonstrated and a squary visit a bit because an area.
a. Cracks or displacement		1/65	**************************************
b. Minor spalling (<1")	`	7	
c. Major spalling (rebars exposed)			7 - 1 1
d. Joint failures			-
e. Water tightness			
Metal pipe condition			
Control valve			
a. Operational/exercised			

Maintenance Item	Satisfactory	Unsatisfactory	Comments
b. Chained and locked		NO	
Pond drain valve			
a. Operational/exercised			
b. Chained and locked			
Outfall channels functioning		NO	
Other (specify)	***************************************		
3. Permanent Pool (Wet Ponds)			
Undesirable vegetative growth		VEC	
Floating or floatable debris removal required		120	
Visible pollution		VES	
Shoreline problem		TIEC	
Other (specify)		- yk-> -	
. Sediment Forebay			
Sedimentation noted DN KNOWN			
Greater than 50% of storage volume remaining	f		***************************************
Dry Pond Areas			
Vegetation coverage adequate		OVER GROW	41
Undesirable vegetative growth		V65	<i>YU</i>
Undesirable woody vegetation		105	
Low flow channels clear of obstructions			***************************************
Standing water or wet spots		1,60	
Sediment and/or trash accumulation		Yes !	
Other (specify)			
Condition of Outfalls	-		
Riprap failures	 		~~~
Slope erosion	 		
Storm drain pipes	 		
Endwalls/Headwalls	 		the second state of the se
Other (specify)			
Other	 		
Complaints from residents (odors, insects, other)	 		
Aesthetics (graffiti, algae, other)		ye	***************************************
Conditions of maintenance access routes			******
Signs of hydrocarbon build-up	 		· · · · · · · · · · · · · · · · · · ·
Any public hazards (specify) // RTY	<u> </u>		· · · · · · · · · · · · · · · · · · ·
		410	
Vegetation healthy and growing Wetland maintaining 50% surface area coverage of		NO	
wetland plants after the second growing season. (If unsatisfactory, reinforcement plantings needed)			
Survival of desired wetland plant species distribution according to landscaping plan?			
Evidence of invasive species			· · · · · · · · · · · · · · · · · · ·

Appendix E: Maintenance Inspection Checklist

Satisfactory	Unsatisfactory	Comments
nd	· · · · · · · · · · · · · · · · · · ·	
	į	

Appendix E: Maintenance Inspection Checklist Infiltration Basins and Trenches - WOODSORKET "As Built" Plans Available? UN KNOWN Date/Time: Days Since Previous Rainfall and Rainfall Amount: Maintenance Item Satisfactory Unsatisfactory Commente 1. Debris Cleanout Basin bottom or trench surface clear of debris Inlet/Inflow pipes clear of debris Overflow spillway clear of debris Outlet clear of debris 2. Sediment Traps or Forebays Sedimentation noted Greater than 50% of storage volume remaining 3. Vegetation (Basins) Mowing performed as necessary 110 No evidence of erosion 4. Dewatering Basin/Trench dewaters between storms 100 Drawdown time does not exceed 36 to 48 hours 190 5. Sediment Accumulation Approximate depth of accumulated sediment 6. Inlets NO Good condition No evidence of erosion 7. Outlet/Overflow Spiliway Good condition, no need for repair No evidence of erosion 8. Aggregate Repairs (Trench) Surface of aggregate clean Top layer of stone does not need replacement Trench does not need rehabilitation 9. Structural Repairs Embankment in good repair Site slopes are stable

No evidence of erosion

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Comments
10. Fences/Access Repairs 110 FENCE	<u> </u>		
Fences in good condition			***************************************
No damage which would allow undesired entry			
Access point in good condition		~	***************************************
Locks and gate function property			
'o Be Completed By (Date):	· .		
•			

Project/Location: HOLLY SPRINGS
"As Built" Plans Available? IS
Date/Time: 3/13/67
Days Since Previous Rainfall and Rainfall Amount:
Inspector: LARRY FIN RIGHT

Maintenance Item	Satisfactory	Unsatisfactory	Comments
1. Debris Cleanout		·····	/
Basin bottom or trench surface clear of debris		NO NEEDS	CLEANING (ST
Inlet/Inflow pipes clear of debris		NO	
Overflow spillway clear of debris		No	
Outlet clear of debris		110	
2. Sediment Traps or Forebays			
Sedimentation noted			
Greater than 50% of storage volume remaining			
3. Vegetation (Basins)			. ,
Mowing performed as necessary		NO NE	EDS CHANIN
No evidence of erosion			
4. Dewatering			
Basin/Trench dewaters between storms	OK		
Drawdown time does not exceed 36 to 48 hours			
5. Sediment Accumulation		-	r
Approximate depth of accumulated sediment	-		
. Inlets			
Good condition		NEEDS (HERNING
No evidence of erosion			
. Outlet/Overflow Spillway			Λ · Λ
Good condition, no need for repair		SCREEN V	BENT UP NEED
No evidence of erosion			
. Aggregate Repairs (Trench)			# + + +
Surface of aggregate clean		?	
Top layer of stone does not need replacement	.	•	
Trench does not need rehabilitation			
Structural Repairs			
Embankment in good repair		7	
Site slopes are stable			
No evidence of erosion			
	.~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Comments
Fences/Access Repairs NO FENCE		1	
Fences in good condition			Annan marana da Aranda anno atro-esta de server
No damage which would allow undesired entry			
Access point in good condition			
Locks and gate function property			volumbles, m. 10 mm 10 m
o Be Completed By (Date):	•		

Project/Location: Lowes / Diameno ALL RD
"As Built" Plans Available? VES
Date/Time: 2/13/07 3:39 Pm
Days Since Previous Rainfall and Rainfall Amount:
Inspector: LARRY ENRIGHT
,

Maintenance Item	Satisfactory	Unsatisfactory	Comments
1. Debris Cleanout			1222
Basin bottom or trench surface clear of debris		NEEDS CIE	ue
Inlet/Inflow pipes clear of debris		NEED CLEAN, N	
Overflow spillway clear of debris		No	*
Outlet clear of debris		No	
2. Sediment Traps or Forebays			
Sedimentation noted		LOTS OF SANI	Tal Barran
Greater than 50% of storage volume remaining	OK	, J. 18-1	LANC DOLLOR
. Vegetation (Basins)		A	
Mowing performed as necessary		n/a	
No evidence of erosion		VERY LITTLE	
. Dewatering		very com	II
Basin/Trench dewaters between storms	OK	A	
Drawdown time does not exceed 36 to 48 hours			**************************************
Sediment Accumulation		And the second s	· · · · · · · · · · · · · · · · · · ·
Approximate depth of accumulated sediment			UNKNOWN
Inlets	1		An annimation and a state of the state of th
Good condition	OK		•
No evidence of erosion	nu	***************************************	سيد چيد و ده در پولود سازه اي واقعال د او در د وي. ديو خود در د در پارسود د در د در
Outlet/Overflow Spillway			
Good condition, no need for repair		NO	BROWEN CEMENT ON
No evidence of erosion	OK		p0.00
Aggregate Repairs (Trench)	1		The state of the s
Surface of aggregate clean		NO	**************************************
Top layer of stone does not need replacement			
Trench does not need rehabilitation			
Structural Repairs			
Embankment in good repair	OK		
Site slopes are stable	OK		
No evidence of erosion	NK		

Maintenance Item	Satisfactory	Unsatisfactory	Comments
0. Fences/Access Repairs			·····
Fences in good condition	OK		
No damage which would allow undesired entry	04		**************************************
Access point in good condition	OK.		
Locks and gate function property	OK		·····

Embankment in good repair Site slopes are stable No evidence of erosion

Project/Location: ()/CEGON /	UE_		and the same of th
"As Built" Plans Available? KNOWN			
Date/Time: 4/13/07			
Days Since Previous Rainfall and Rainfall Amount:			
1000 611			······································
Inspector: http://www.	7	· · · · · · · · · · · · · · · · · · ·	
·			
Maintenance Item	Satisfactory	Unsatisfactory	Comments
1. Debris Cleanout	·	ulii sin uu	
Basin bottom or trench surface clear of debris		VERU NU	ER CROWN
Inlet/Inflow pipes clear of debris		TREAL IN	FRONDS
Overflow spillway clear of debris	***************************************	OVER CA	navn
Outlet clear of debris		No	0.070
2. Sediment Traps or Forebays		<u> </u>	
Sedimentation noted			
Greater than 50% of storage volume remaining			
3. Vegetation (Basins)			
Mowing performed as necessary		NO	
No evidence of erosion			3 ROUN TO SEA
4. Dewatering	· · · · · · · · · · · · · · · · · · ·	70 0007 1	310000 / 501
Basin/Trench dewaters between storms		WAS EM	Post
Drawdown time does not exceed 36 to 48 hours		00,10 2,	77
5. Sediment Accumulation	·····	<u>-</u>	
Approximate depth of accumulated sediment		NOT SE	CAL
6. Inlets	······································	11201 -08	27.0
● Good condition	T	ROCKED V	BU TREES
No evidence of erosion		1101 SEFA	1191223
7. Outlet/Overflow Spillway	···············	0.0 - 4.10	· · · · · · · · · · · · · · · · · · ·
Good condition, no need for repair		MISSING TO	CRATE
No evidence of erosion	/	7	1 (de) 11 (de)
8. Aggregate Repairs (Trench)			
Surface of aggregate clean			
Top layer of stone does not need replacement			
Trench does not need rehabilitation			
9. Structural Repairs			

Appendix E: Maintenance Inspection Checklist

Maintenance Item MIO FERCE	Satisfactory	Unsatisfactory	Comments
10. Fences/Access Repairs			
Fences in good condition			
No damage which would allow undesired entry			
Access point in good condition		.,,,,,,	To the second
Locks and gate function property			
To Be Completed By (Date):			

• • • • • • • • • • • • • • • • • • • •					
Project/Location: YARK DEWE	/ imer j	TOD AU	6	CARLAND	GROVE
"As Built" Plans Available?					-
Date/Time: 2/13/07					
Days Since Previous Rainfall and Rainfall Amount:					•
Inspector: LARRY ENRIGHT					
Maintenance Item	Satisfactory	Unsatisfac	tory	Comments	7.60
i. Debris Cleanout	h	<u> </u>	···	1	
Basin bottom or trench surface clear of debris		VERY	Ov	L CROWN	,
Inlet/Inflow pipes clear of debris		NEED	VO	CIEDN FOR	TUS
Overflow spillway clear of debris				The state of the s	
Outlet clear of debris			~~~~~		
2. Sediment Traps or Forebays			•		
Sedimentation noted				**************************************	
Greater than 50% of storage volume remaining					
3. Vegetation (Basins)					
Mowing performed as necessary					
No evidence of erosion				,	
4. Dewatering			·1.		
Basin/Trench dewaters between storms		1		**************************************	
Drawdown time does not exceed 36 to 48 hours				***************************************	
5. Sediment Accumulation			·····		
Approximate depth of accumulated sediment			T		
6. Inlets		1			
Good condition					
No evidence of erosion					
7. Outlet/Overflow Spillway	·····		t	·	
Good condition, no need for repair			7		
No evidence of erosion					
8. Aggregate Repairs (Trench)				~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
Surface of aggregate clean				**************************************	
Top layer of stone does not need replacement					
Trench does not need rehabilitation				*** *	
9. Structural Repairs	-	1,	$\neg \vdash$		
Embankment in good repair	Ις		$\neg \neg$	***************************************	7
Site slopes are stable			\top	······································	
No evidence of erosion		Y			7

Appendix E: Maintenance Inspection Checklist

	Maintenance Item	Satisfactory	Unsatisfactory	Commente
No damage which would allow undesired entry Access point in good condition Locks and gate function property trions to Be Taken:	0. Fences/Access Repairs	·	<u> </u>	
Access point in good condition Locks and gate function property cions to Be Taken:	Pences in good condition		<u> </u>	
Locks and gate function property ctions to Be Taken:	No damage which would allow undesired entry			,
tions to Be Taken:	Access point in good condition			
tions to Be Taken:	Locks and gate function property			
	n Ba Completed By (Date)			
	· .			

Appendix E: Maintenance Inspection Checklist Stormwater Ponds and Wetlands

Project/Location: CVS / PARK EAST DRIVE
"As Built" Plans Available?
Date/Time: 2/13/07
Days Since Previous Rainfall and Rainfall Amount:
Inspector: LACLY ENGIGHT

Maintenance Item	Satisfactory	Unsatisfactory	Comments
. Embankment and Emergency Spillway		·	
 Vegetation and ground cover adequate 		NEEDS TO L	E CLEANER)
Embankment erosion	NO		
Animal burrows	NONE SEED		
 Unauthorized planting 	No		
 Cracking, bulging, or sliding of embankment/dam 	NA		
a. Upstream face	, ,		
b. Downstream face			,
c. At or beyond toe			
d. Emergency spillway	/		
Pond, toe & chimney drains clear and functioning	NA		
Seeps/leaks on downstream face	NI/A		
Slope protection or riprap failure	NONE		
Vertical/horizontal alignment of top of dam "As-Built"	NA		
Emergency spillway clear of obstructions and debris	N/A		
Other (specify)	7		
Riser and Principal Spillway N/A			
Low flow orifice obstructed			
Low flow trash rack obstructed with debris			
Weir trash rack obstructed with debris			
Excessive sediment accumulation insider riser			
Concrete/masonry condition riser and barrels			
a. Cracks or displacement			
b. Minor spalling (<1")			
c. Major spalling (rebars exposed)			
d. Joint failures			
e. Water tightness			
Metal pipe condition			
Control valve			

Maintenance Item	Satisfactory	Unsatisfactory	Comments
b. Chained and locked	NA		
Pond drain valve	NIS		
a. Operational/exercised	13/A		
b. Chained and locked	NA		
Outfall channels functioning	NA		
Other (specify)			
3. Permanent Pool (Wet Ponds)			•
Undesirable vegetative growth		VES	
Floating or floatable debris removal required		SME	
Visible pollution		,	
Shoreline problem		TREES/EST	
Other (specify)			
4. Sediment Forebay	L		
Sedimentation noted W SEEN /	ROZEN		
Greater than 50% of storage volume remaining			
5. Dry Pond Areas			
Vegetation coverage adequate			***************************************
Undesirable vegetative growth			· · · · · · · · · · · · · · · · · · ·
Undesirable woody vegetation			
Low flow channels clear of obstructions			
Standing water or wet spots			
Sediment and/or trash accumulation			
Other (specify)			
6. Condition of Outfalls		•.	A TOTAL CONTRACTOR OF THE PARTY
Riprap failures			
Slope erosion			
Storm drain pipes			<u> </u>
Endwalls/Headwalls			<u></u>
Other (specify)			Athenia
7. Other			
Complaints from residents (odors, insects, other)			***************************************
Aesthetics (graffiti, algae, other)			***************************************
Conditions of maintenance access routes			***************************************
Signs of hydrocarbon build-up			
Any public hazards (specify)			
Wetland Vegetation		L	
Vegetation healthy and growing	T		
Wetland maintaining 50% surface area coverage of			
wetland plants after the second growing season. (If			
unsatisfactory, reinforcement plantings needed)			
 Survival of desired wetland plant species distribution according to landscaping plan? 			
Evidence of invasive species			

Appendix E: Maintenance Inspection Checklist

Maintenance Item N/A	Satisfactory	Unsatisfactory	Comments
Maintenance of adequate water depths for desired wetland plant species.			
Harvesting of emergent plantings needed			
 Have sediment accumulations reduced pool volume significantly or are plants "choked with sediment. 		·	
Other (specify)			•
Actions to Be Taken:			
To Be Completed By (Date):			

Project/Location: #OBINSAN ST (SCHOOL)
"As Built" Plans Available?
Date/Time: 2/13/07
Days Since Previous Rainfall and Rainfall Amount:
Inspector: LARRY ENRIGHS
The state of the s

Maintenance Item	Satisfactory	Unsatisfactory	Comments
1. Debris Cleanout		<u> </u>	<u></u>
Basin bottom or trench surface clear of debris		No TIRE	/BRUSH/S
Inlet/Inflow pipes clear of debris	OK	1	
Overflow spillway clear of debris	ok		
Outlet clear of debris	OK		
2. Sediment Traps or Forebays			<u> </u>
Sedimentation noted	OK		
Greater than 50% of storage volume remaining			
3. Vegetation (Basins)		<u> </u>	
Mowing performed as necessary		NO TAIL	WEEDS/CODA
No evidence of erosion		/ / /	The state of the s
. Dewatering		· ************************************	
Basin/Trench dewaters between storms	OK		
Drawdown time does not exceed 36 to 48 hours			
. Sediment Accumulation			
Approximate depth of accumulated sediment	OK		
Inlets			**************************************
Good condition	OK		
No evidence of erosion	(VX		
Outlet/Overflow Spillway	 		
Good condition, no need for repair	100		
No evidence of erosion	M		**************************************
Aggregate Repairs (Trench)			The state of the s
Surface of aggregate clean	0%		
Top layer of stone does not need replacement	nK		
Trench does not need rehabilitation	OV		· · · · · · · · · · · · · · · · · · ·
Structural Repairs			***************************************
Embankment in good repair	OU		
Site slopes are stable	OV.		-
No evidence of erosion	01/		

Appendix E: Maintenance Inspection Checklist

On Fences / Access Repairs Fences in good condition No damage which would allow undesired entry Access point in good condition Locks and gate function property Actions to Be Taken: To Be Completed By (Date):	Fences in good condition No damage which would allow undesired entry Access point in good condition Locks and gate function property Actions to Be Taken:	Maintenance Item	Satisfactory	Unsatisfactory	Comments
No damage which would allow undesired entry Access point in good condition Locks and gate function property Actions to Be Taken:	No damage which would allow undesired entry Access point in good condition Locks and gate function property Actions to Be Taken:	10. Fences/Access Repairs		<u> </u>	
Access point in good condition Locks and gate function property Actions to Be Taken:	Access point in good condition Locks and gate function property Actions to Be Taken:	Fences in good condition	OK	ļ	· · · · · · · · · · · · · · · · · · ·
Locks and gate function property Actions to Be Taken:	Locks and gate function property Actions to Be Taken:	No damage which would allow undesired entry			
Actions to Be Taken:	Actions to Be Taken:	Access point in good condition			
Actions to Be Taken:	Actions to Be Taken:	Locks and gate function property			

Project/Location: TACA LANG LEDGE WG	000
	200
"As Built" Plans Available?	
Date/Time: 2/13/07	
Days Since Previous Rainfall and Rainfall Amount:	

Inspector: LARRY ENRIGHT	
	TO A SECTION OF SET THE WAY WE WILL

Maintenance Item	Satisfactory	Unsatisfactory	Comments
1. Debris Cleanout	······································		
Basin bottom or trench surface clear of debris	OK		
Inlet/Inflow pipes clear of debris		SOME TRE	65 BRUSH
Overflow spillway clear of debris		Some TR	ELS / BRUSH
Outlet clear of debris		Some TA	EKE / RRUS
2. Sediment Traps or Forebays			
Sedimentation noted	OK		
Greater than 50% of storage volume remaining	OK		
3. Vegetation (Basins)			
Mowing performed as necessary	VES		***************************************
No evidence of erosion	NO		
. Dewatering		······································	**************************************
Basin/Trench dewaters between storms	NO WATE	R	
Drawdown time does not exceed 36 to 48 hours			
Sediment Accumulation			, , , , , , , , , , , , , , , , , , , ,
Approximate depth of accumulated sediment	NONE		
Inlets			
Good condition		Some SMA	KER
No evidence of erosion			
Outlet/Overflow Spillway			
Good condition, no need for repair	OK		
No evidence of erosion			
Aggregate Repairs (Trench)	,		
Surface of aggregate clean	OK		,
Top layer of stone does not need replacement			
Trench does not need rehabilitation			·
Structural Repairs	·		
Embankment in good repair	RX		
Site slopes are stable			
No evidence of erosion	,		

Appendix E: Maintenance Inspection Checklist

Maintenance Item	Satisfactory	Unsatisfactory	Comments
0. Fences/Access Repairs NO FENCE			
Fences in good condition			· · · · · · · · · · · · · · · · · · ·
No damage which would allow undesired entry			
Access point in good condition			<u> </u>
Locks and gate function property			······································
•			
·	·		
) Be Completed By (Date):			
Be Completed By (Date):			
) Be Completed By (Date):			

Project/Location: WALMART / DIAMOND HILL RD
"As Built" Plans Available?
Date/Time: 2/15/07 335 PM
Days Since Previous Rainfall and Rainfall Amount:
Inspector: LARRY ENRIGHT

Maintenance Item	Satisfactory	Unsatisfactory	Comments
1. Debris Cleanout		alanda wata da kan da	
Basin bottom or trench surface clear of debris		TRASH.	PAPER TRASH
Inlet/Inflow pipes clear of debris		TRASH	
Overflow spillway clear of debris		NA	
Outlet clear of debris		Some TRASH	
2. Sediment Traps or Forebays N/A			
Sedimentation noted			
Greater than 50% of storage volume remaining			
3. Vegetation (Basins)			
Mowing performed as necessary	OK		**************************************
No evidence of erosion	OK OK		M-14-1-1-Material
4. Dewatering N/A			
Basin/Trench dewaters between storms		-	
Drawdown time does not exceed 36 to 48 hours			
5. Sediment Accumulation		***************************************	
Approximate depth of accumulated sediment		•	
i. Inlets			
Good condition	OK		
No evidence of erosion	oK		
. Outlet/Overflow Spillway			
Good condition, no need for repair	OK		
No evidence of erosion	OK		
Aggregate Repairs (Trench)			
Surface of aggregate clean			
Top layer of stone does not need replacement			
Trench does not need tehabilitation		***************************************	
Structural Repairs			
Embankment in good repair	OK		
Site slopes are stable	OK		**************************************
No evidence of erosion	OK		

Appendix E: Maintenance Inspection Checklist

Maintenance Item 10. Fences/Access Repairs	Satisfactory	Unsatisfactory	Comments
Fences in good condition	OK		
No damage which would allow undesired entry	OK		
Access point in good condition	OK		
Locks and gate function property	OX		

To Be Completed By (Date):